



CSA Certification: Fabricators

- There are 4 key elements to a fabricator certification program:
 1. Qualified welder(s)
 2. Qualified welding procedures
 3. Qualified welding supervisor(s)
 4. Qualified welding engineer(s)
- In practical terms, this means that a welding fabricator must have:
 - Competent individuals making the welds, who are...
 - Following proven and documented “recipes”, in a shop...
 - Overseen by competent “bosses”.
- When all three are in place, high quality welds will result!
 - Certification ensures these key elements are in place and working

