



CSA W47

- Fabricators can be certified to 1 of 3 “divisions”.

	Division 3	Division 2	Division 1
Qualified Welders	Yes	Yes	Yes
Qualified Welding Supervisor(s)	Yes	Yes	Yes
Qualified Welding Engineer(s)	No	Yes – Retained	Yes - Employed
Accepted Welding Procedures	Yes	Yes	Yes

